

Supplementary Materials




Figure S1. Appearance of the coatings after annealing at a temperature of 1000 °C and exposures of 10–300 min, and after annealing at 1000 °C followed by cooling to 20 °C and high-temperature annealing at 1300 °C.