catalysts

MDPI

Supplementary Materials

Photoelectrocatalytic Degradation of Congo Red Dye with Activated Hydrotalcites and Copper Anode

Sara Argote-Fuentes [1], Rossy Feria-Reyes [2], Esthela Ramos-Ramírez [2,*], Norma Gutiérrez-Ortega [3,*] and Gustavo Cruz-Jiménez [4]

[1] Doctoral Program in Water Science and Technology, Engineering Division, Guanajuato Campus, University of Guanajuato. 77 Juarez St, Downtown, Guanajuato, GTO 36000. Mexico; sg.argotefuentes@ugto.mx

[2] Chemistry Department: Natural and Exact Sciences Division, Guanajuato Campus, University of Guanajuato. w/n Noria Alta, Guanajuato, GTO 36000, Mexico; rossyfr@gmail.com

[3] Department of Civil and Environmental Engineering, Engineering Division, Guanajuato Campus, University of Guanajuato. 77 Juarez St, Downtown, Guanajuato, GTO 36000. Mexico.

[4] Pharmacy Department, Natural and Exact Sciences Division, Guanajuato Campus, University of Guanajuato. w/n Noria Alta, Guanajuato, GTO 36050, Mexico, cruzg@ugto.mx

* Correspondence: ramosre@ugto.mx (E.R.-R.); normagut@ugto.mx (N.G.-O.); Tel.: +52-4737320006 (1457 and 2227 telephone extension number)



(**a**) (**b**)

Figure S1. (**a**) Linear correlation of the calibration curve by high-performance liquid chromatography (HPLC) of the industrial-grade synthetic dye Congo Red and (**b**) solution of the calibration curve.



Figure S2. Chromatograms of the Liquid chromatography–mass spectrometry (LC–MS) analysis of Congo red after degradation (**a**) Congo Red standard, (**b**) catalyst, (**c**) photocatalyst, (**d**) electrocatalyst, (**e**) photoelectrocatalyst, and (**f**) possible degradation products of Congo red in the presence of hydrotalcites.



Figure S3. (**a**) Solutions of dye at different concentrations for degradation; (**b**) solutions after degradation by the process of photocatalysis; (**c**) solutions after degradation by photoelectrocatalysis.



Figure S4. Diagram of the photoelectrocatalysis process.