

Correction

Correction: Czapik, P. Microstructure and Degradation of Mortar Containing Waste Glass Aggregate as Evaluated by Various Microscopic Techniques. *Materials* 2020, 13, 2186

Przemysław Czapik 

Department of Building Engineering Technologies and Organization, Kielce University of Technology, Al. Tysiąclecia Państwa Polskiego 7, 25-314 Kielce, Poland; p.czapik@tu.kielce.pl

The author wishes to make the following correction to this paper [1]. Due to the duplication of the same diagrams in Figures 8 and 9, replace



Citation: Czapik, P. Correction: Czapik, P., Microstructure and Degradation of Mortar Containing Waste Glass Aggregate as Evaluated by Various Microscopic Techniques. *Materials* 2020, 13, 2186. *Materials* 2021, 14, 159. <https://doi.org/10.3390/ma14010159>

Received: 19 December 2020
Accepted: 29 December 2020
Published: 31 December 2020

Publisher’s Note: MDPI stays neutral with regard to jurisdictional claims in published maps and institutional affiliations.



Copyright: © 2020 by the author. Licensee MDPI, Basel, Switzerland. This article is an open access article distributed under the terms and conditions of the Creative Commons Attribution (CC BY) license (<https://creativecommons.org/licenses/by/4.0/>).




Figure 9. (a) extensively cracked region in the microstructure of the mortar containing waste glass (b) region of porous gel (BSE); EDS analysis at points I and II, (c) cracks in the gel.

with




Figure 9. (a) extensively cracked region in the microstructure of the mortar containing waste glass (b) region of porous gel (BSE); EDS analysis at points I and II, (c) cracks in the gel.

The author would like to apologize for any inconvenience caused to the readers by these changes. This change will not affect the results of the article.

Reference

1. Czapiak, P. Microstructure and Degradation of Mortar Containing Waste Glass Aggregate as Evaluated by Various Microscopic Techniques. *Materials* **2020**, *13*, 2186. [[CrossRef](#)]